









Precision laser scan and 2-D report



Report generated by: Steve Traynor
stevet@qcgroup.com
952-746-5864
4/2/2014

Data Alignment: Best Fit
QC Work Order: Gutter Clip















Table Type Data Color Map (Reference Surface)

Cmp Object(s)	Gutter_Clip_loc.txt, Gutter_Clip_loc.txt (2)
Ref	Ref_Geom.IGS (2)
Units	Inches
CSYS	World
Alignment	rotation (3) (alignment group 2), translation (3) (alignment group 1)

#Points	285601
Mean	-0.0015
StdDev	0.0114
Max Error	0.0388
Min Error	-0.0291
Profile of a surface	0.0776
Pts within +/- (1 * Std Dev)	203791 (71.3551%)
Pts within +/- (2 * Std Dev)	267373 (93.6177%)
Pts within +/- (3 * Std Dev)	284989 (99.7857%)
Pts within +/- (4 * Std Dev)	285601 (100.0000%)
Pts within +/- (5 * Std Dev)	285601 (100.0000%)
Pts within +/- (6 * Std Dev)	285601 (100.0000%)